FULL BARRIER REPORT

Barrier Number	N1-104	
Survey Page Number	15	
Location Descriptor	Lobby Wall Sconces	
Removal Difficulty	Q	
Existing Condition	4.75" projection, 64" high	
Phase Code	6	DETAILED
Use Code	Ρ	REPORT
Severity Code	A	OPTION 1
DOJ Code (location type)	2	SBS
ADAAG/UFAS Reference	4.4.2	
Barrier Text	Protruding Object with bottom between 27" and 80" AFF projects more than 4" from wall or 12" from post.	
Recommendation Text	Remove Protruding Object. Install new item of recessed, semi- recessed, or other design which alleviates hazard. If required to be accessible, comply with reach ranges, Clear Floor Space, etc.	
Full BR Rough Estimate	\$	1,480.00
Administrative Method	Locate furniture, planter or other cane-detectable object under or adjacent to the protruding object.	
Admin. Method Rough Estimate	\$	
Notes	Though there are 9 wall sconces, one currently has an ashtray below. If ashtray is removed, there will be 9 protruding objects	